



Mary Washington Healthcare

Mary Washington Hospital Rappahannock Wound Healing Center

Hyperbaric Oxygen Chamber Patient Overview

Hyperbaric Oxygen Treatment is a treatment in which the patient breathes oxygen inside a pressurized chamber. The treatment quickly delivers high concentrations of oxygen to the bloodstream. This assists in the healing process of wounds and is effective in fighting certain types of infections.

When you arrive at the center.

After an initial consultation and exam by a specialized Wound Care Physician at the center, you will be ready to begin your therapy. When you arrive, you will receive complete instructions regarding your treatment. Before starting, you will change into a 100% cotton garment provided by the center. For safety reasons, no other clothing may be worn inside the hyperbaric oxygen therapy chamber.

What to expect during treatment.

Once you are comfortably inside the chamber, the pressure will gradually be increased and the temperature will temporarily rise. You may experience fullness in your ears as a result of the increased pressure. The technician will instruct you in ways to help clear the pressure and relieve any discomfort. Most treatment sessions in the chamber last approximately two hours. While undergoing treatment, you may watch tv or videos, simply relax or even sleep.

Getting ready for your visit.

Oxygen is necessary to heal wounds, but it is also a key ingredient in all flammable reactions. Therefore, for safety reasons flammable and inflammatory items are not allowed inside the hyperbaric chamber. Please do not wear or bring the following into the chamber during your treatment.

Makeup
Perfume
Aftershave
Hairspray/hair oils
Nail polish
Alcohol or petroleum based products, such as Vaseline, rubbing alcohol, hair gel, mousse, etc.
Wigs/hairpieces

Cell phones/pagers
Metallic items (such as jewelry, titanium frame eyeglasses, keys, watches, and coins)
Flammable materials or heat producing items (heating pad, lighters, cigarettes)
Hearing aids
Food, gum or candy

If you wear contact lenses, please ask your hyperbaric physician specialist for advice on wearing contact lenses during treatment. Please bring a contact lens holder to all of your appointments.

It is also recommended that patients do not smoke or use tobacco products during the time you are in therapy with us. Tobacco use will prolong or even prevent healing of a wound site due to its constricting effect on the blood vessels in your body.